

## TABLE OF CONTENTS

<b>ABSTRACT</b> .....	ii
<b>ACKNOWLEDGEMENTS</b> .....	iii
<b>TABLE OF CONTENTS</b> .....	iv
<b>LIST OF TABLES</b> .....	vi
<b>LIST OF FIGURES</b> .....	viii
<b>Chapter 1: Introduction</b> .....	1
Research Outline.....	2
<b>Chapter 2: Review of Previous Work</b> .....	4
The Long-Term Performance of Seepage Barriers.....	4
Theoretical Seepage Barrier Performance.....	9
Construction Techniques and Material Properties.....	13
Piping Development in Dams.....	25
Summary.....	39
<b>Chapter 3: Summaries of Case Histories</b> .....	40
Wolf Creek Dam.....	40
Upper and Lower Clemson Diversion Dams.....	58
Wister Dam.....	67
Fontenelle Dam.....	78
Navajo Dam.....	91
Virginia Smith Dam.....	100
New Waddell Dam.....	107
Beaver Dam (Dike 1).....	113
Meeks Cabin Dam.....	119
Mill Creek Dam.....	127
Private Dam Number 1.....	141
Walter F. George Dam.....	149
Mud Mountain Dam.....	157
Jackson Lake Dam.....	166
Twin Buttes Dam.....	172
Chambers Lake Dam.....	180

Manasquan Dam.....	186
West Lewiston Levee.....	197
Camanche Dike-2.....	204
Old Dams with Seepage Barriers.....	213
Summary of Observations and Findings from Case Histories.....	227
<b>Chapter 4: Analyses.....</b>	<b>240</b>
Seepage Analyses on Case Study Dams.....	240
Deformation Analyses on Case Study Dams.....	243
Analyses on Specific Dams.....	245
Analyses on the Effects of Cracks on Barrier Performance.....	277
Summary of Insights from Analyses.....	284
<b>Chapter 5: Potential Failure Modes Associated with Seepage Barriers.....</b>	<b>293</b>
Development of Failure by Piping.....	293
Potential Failure Modes Associated with Seepage Barriers.....	296
Conclusions.....	307
<b>Chapter 6: Summary and Conclusions.....</b>	<b>308</b>
Summary of Work Performed.....	308
Summary of Conclusions.....	309
Recommendations for Further Research.....	315
<b>References.....</b>	<b>317</b>
<b>Appendix A: Details of Deformation Analyses.....</b>	<b>A-1</b>